JAKTZ ONE ARRIVAL (RNAV)   COLUMBUS, OHIO

ARRIVAL ROUTE DESCRIPTION

<u>GETTA TRANSITION (GETTA.JAKTZ1)</u>
<u>JUDDI TRANSITION (JUDDI.JAKTZ1)</u>

KCMH: From JAKTZ on track 045° to RSCOT.

<u>LANDING KCMH RUNWAY 10L:</u> From RSCOT on track 031° to cross SHMDT at 5000, then on track 031° to WATSU, then on track 039° to cross YUKAN at 5000 and at 210K, then on track 039°. Expect RADAR vectors to ILS or LOC RWY 10L approach.
<u>LANDING KCMH RUNWAY 10R:</u> From RSCOT on track 031° to cross SHMDT at 5000, then on track 031° to WATSU, then on track 044° to cross HANTI at 5000 and at 210K, then on track 044°. Expect RADAR vectors to ILS or LOC Rwy 10R approach.
<u>LANDING KCMH RUNWAY 28L/R:</u> From RSCOT on track 063° to OBETZ, then on track 063° to cross ELUPY between 8000 and 9000, then on track 063° to cross EDWIB at or above 7000, then on track 063° to GAGBE, then on track 101° to cross JESCE at 6000 and at 210K, then on track 101°. Expect RADAR vectors to final approach course.

<u>LANDING KLCK:</u> From JAKTZ on track 080° to PAAPP then on track 080°. Expect RADAR vectors to final approach course.

<u>LANDING KOSU:</u> From JAKTZ on track 020° to RIBLE, then on track 020°. Expect RADAR vectors to final approach course.

<u>LANDING KTZR:</u> From JAKTZ on track 045° to WWRRN, then on track 045°. Expect RADAR vectors to final approach course.